## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: David L. Marvit et al.

U.S. Patent No.: 7,301,528 B2

Issue Date: November 27, 2007

Serial No.: 10/807,569

Filing Date: March 23, 2004

Confirmation No.: 4255

Title: Distinguishing Tilt and Translation Motion Components in

Handheld Devices

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted, BAKER BOTTS L.L.P.

Attorneys for Applicants

Customer No.: 05

Phone: (214) 953-6986

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.: 7,301,528 B2

Dated: November 27, 2007 Inventor: David L. Marvit et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5, Line 7, after "28c;" delete "rangefinders" and insert -- rangefinders --. Column 28, Line 53, after "dimension" delete ".".

Mailing Address of Sender:

Patent No.

7,301,528 B2

Baker Botts L.L.P. 2001 Ross Avenue, Suite 600 Dallas, Texas 75201-2980